

## CÓDIGO

## MODELO

## AIWA

KFT 3AA 294X

AR 205  
(Vide Equivalente CCE-49)

KFT 4AA 271X

AR 295RH

KFT 2AA 293X

AR-145 (Vide Equivalente CCE-53)

## BAYSONIC

@ FCK 14A028

CB -14 A ( Vide Equivalente Semivox - SS-04 )

154 - 165D

CB - 20

FCM 20A016

CB 20 A / SINGER TV 3920

TLF 70162

## BROKSONIC

FCC 1415AL

GTV 4545 LSTC / Foco Baixo (duplicidade) **CTVG 4545LSTC**

FCC 2015AL

GTV 5454

FCC 2015FL

CTVG-5454-LST

( Foco ALTO )

GTV 4545 LSTC / Foco Alto (duplicidade)

3.219.004

GT 5454 LST

3213002

4545LST 14"

3213003

KFS60282

CTVL4545 14"

DCF 2077

4545 LSB

BSC 23-1108

BROKSONIC CTVC - 4545

## CCE , BLUE SKY, DAEWOO, PROVIEW

TAT 1401 A

HPS 1415 B, 1415 C  
HPS 1425 A, 1425 B  
HPS 1450 B, 1465, 1465 A, 1465 B

TAT 1402 A

HPS 1465 Z, 1470 B, 1470 K, 1470 Z, 1470 ZJ, 1490 C  
HPS 1485, 1485 B, 1485 G, 1485 ZG  
HPS 1490, 1490 B, 1490 H

TAT 1402 B

TAT 1402 C

TAT 1403 A

HPS 1465 C, 1465 ZC, 1465 ZD, 1465 ZG, 1465 ZH  
HPS 1470 ZC, 1470 ZD, 1470 ZG, 1470 ZH  
HPS 1485 D, 1485 ZC, 1485 ZD  
HPS 1490 D, 1490 ZC, 1490 ZD

TAT 1403 B

TAT 1404 A

HPS 1465 ZE, 1465 ZF, 1465 ZI  
HPS 1470 ZI, 1470 ZE / ZF  
HPS 1485 E, 1485 I, 1485 F, 1485 ZE, 1485 ZF, 1485 ZI  
HPS 1490 CD,1490 E,1490 F,1490 I,1490 ZE,1490 ZF,1490 ZI  
HPS 14B, 14E, 14R, 14RB, 14RC, 14RD  
HPS 1470 AA, 1470AP, 1470 BB, 1470 CC, 1470 DD, 1470 EE,  
HPS 1470FF, 1470P, 1470Q, 1470R, 1470S,1470T,1470U  
HPS 1480, 1480 B, 1480 C, 1480 D  
HPS 1481, 1481 B, 1481 C  
HPS 1492 C

TAT 1405 A

TAT 1405 B

TAT 1405 D

TAT 1406 A

HPS 1401, 1470 V, 1481 E, 1481 Y

TAT 1407 A

HPS 1401D, 1401

TAT 1407 B

HPS 1492

CODIGO	MODELO
<b>TAT 1409 A</b>	HPS 1401B, 1401C, 1401H, 1402B, 1402E, 1402F, 1403, 1402C
TAT 1409 B	HPS 1403B, 1403C, 1403D, 1404, 14BLK, 14BLKB, 14BLKC
TAT 1409 C	MT14, TVC 141
TAT 1409 D	
<b>TAT 1412A</b>	HPS 141B, 141C, 141D, 141G, 142B, 1405, 1407F, 1407G, 1407E
	HPS 1407S, 1423, MT14NEW, 1407B, 1405B
<b>TAT 1414 A</b>	HPS 14BPS
<b>TAT 1420 A</b>	CCE 1405 H
<b>154 - 179M</b>	HPS 2980, 2990, 2990B
FBT 2990 A (TRIPLICIDADE)	( Vide Equivalente Goldstar - GD-03 / LG - 03 )
TAT 2990A	
<b>DCF 1577</b>	HPS 1491, 1495, GTV 4545 LSTC
DCF 1577 A1	( Vide Equivalente Precision - PX-02) - NISATO 1445 NCT
<b>TAT 2001 A</b>	HPS 2010 B, 2025 A, 2025 B, 2050 B, 2065, 2070
	HPS 2065, 2065 Z, 2065 ZB, 2065 ZC, 2065 ZD
<b>TAT 2002 A</b>	HPS 2070, 2070 B, 2070 Z, 2070 ZB, 2070 ZC
TAT 2002 B	HPS 2085, 2085 B, 2085 C, 2085 ZB, 2085 ZC
	HPS 2090, 2090 B, 2090 C, 2090 ZB, 2090 ZC
<b>TAT 2003 A</b>	HPS 2065 ZD, 2065 ZE, 2070 ZD, 2070 ZE, 2070 ZF D/E/F, 2090FD
	HPS 2085 D, 2085 E, 2085 F, 2090 B, 2090D, 2090 E, 2090 F, 2090AP
	HPS 2070P, 2070Q, 2070R, 2080F, 2080R, 2081B, 2080H, 2081D
<b>TAT 2004 A</b>	HPS 2070X, 2070 ZD, 2070 ZE, 2070 ZF
TAT 2004	HPS 2085 D, 2085 E, 2085 F, 2090 B, 2090 D
TAT 2004B	HPS 2090 E
<b>TAT 2005 A</b>	HPS 2080 C, 2080 E
<b>TAT 2006 A</b>	
TAT 2006 B	HPS 2070 S, 2070 V, 2080 B, 2081, 2081 C, 2080
TAT 2006 C	
TAT 2006 D	
<b>TAT 2007 A</b>	HPS 2080 D
<b>TAT 2008 A</b>	HPS 2092, 2092 B, 2092 C, 2092 D
<b>TAT 2009 A</b>	HPS 1402 C, 2001, 2001 B, 2001 C, 2001 D, 2002, 2002 D, 2003,
TAT 2009 B	HPS 2004 A/B, 2006, 2003 B/C, 2009 D, 2001 I
TAT 2009 C	MATSUI / MT-20
TAT 2009 D	BLUE SKY - TV 20 BLK
TAT 2009 E	
TLF 032013306	
<b>TAT 2011</b>	HPS 2007C, 2023, MT20NEW
<b>TAT 2012</b>	HPS 2005, 2005G, 2007, 2007F, 2007H, 2007S, 2008,
	JC20, HPS 2071, HPS 2044.
<b>TAT 2020</b>	HPS 2005 H
@ FSV 20 B 013	BLUE SKY - TC-2033V (Vide Equivalente Cinerel - CN-04)

CÓDIGO	MODELO
	<b>CCE , BLUE SKY, DAEWOO, PROVIEW</b>
<b>FCM 2015 CL</b>	HPS 2010, 2010A, 14 ( 10 Pinos )
TLF 70018A	( Vide Equivalente Samsung - SS-17 )
<b>DCF 2077</b>	HPS 20 VR, 2091, 2095
DDF 9802A	( Vide Eq.Paxan e Precision - PX-03/ Philco - PC-07/ Telefunken - TF-03)
KFS 61115	NISATO 2045 NCT - BROOKSONIC - 4545 LSB.
<b>TAT 2101 A</b>	HPS 2181 A, 2181 B, 21E
<b>TAT 2102 A</b>	HPS 20 EP, 21 EB
@ <b>BSC 23-6910</b>	BLUE SKY - 1433 (Vide Equivalente Ceneral - CN - 01)
FO 1415 (DNF)	
<b>TAT 2701 A</b>	HPS 2780, 2781B, 2980 (IMPORT.)
<b>TAT 2702 A</b>	HPS 2706, 2706 B
<b>TAT 2704 A</b>	HPS 2706C, 27BLK
<b>TAT 2901 A</b>	HPS 2980, 2981, 2981B, 2981C, 2981D
MSU1FHC506	HPS 2980 (IMPORT.)
MSU1FHG506	
( TRIPLICIDADE )	
<b>TAT 2902 A</b>	HPS 29E "B"
<b>TAT 2903 A/B</b>	HPS 2902, HPS 2901B, HPS 2901
<b>TAT 2904 A</b>	HPS 2904E, 2906 B, 2906C, 2906D , 29BLK , 29BLKB,
TAT 2904B	29BLKC, 29BLKD, 2904A, 2904B
<b>TAT 2907 A/B</b>	HPS 2906E, 2906F, 2910 , 2910B, 2910C, 2910E
<b>TAT 2908 A</b>	HPS 2908 C
<b>TAT 2908 B</b>	HPS 2908
TAT 2908C	
<b>FBT 3380</b>	HPS 3380
TAT 3380	
<b>TAT 3401 A</b>	HPS 33 R / 33 RB
<b>KFS 60226 / B</b>	HPS 1425, 1450 A, 1450 R, 1450 C, 1495, 1495 B, 1450 AB, 1495 BR, 1491
	<b>20AV49 (PHILCO USHUAIA - ARGENTINA)</b>
<b>KFS 60266</b>	HPS 2025, 2050 A, 2050 C, 2050 R, 2095, HPS 20
FA 1426	DAYTON DTH 1427 FS
<b>NF 7301</b>	HPS 1415, HPS 14 Polegadas (Foco Baixo)
NF 7302	
(Foco BAIXO)	HPS 1430 R
<b>NF 7401</b>	HPS 20, 2015, 2030 R
FTB 7401C	
<b>TAT 2906B</b>	HPS 2901
@ <b>KFT 3AA 294X</b>	HPS 2003F, TVAR205
	(Vide Equivalente Aiwa - AW-01)
<b>KFT 4AW 332Y</b>	HPS 2912
KFT 4AA 332X	

CÓDIGO	MODELO
	<b>CCE , BLUE SKY, DAEWOO, PROVIEW</b>
@ BSC 28-2101 C 1226216C	BLUE SKY - TC-2932 / 2933 / HPS 2185 FSE (Vide Equivalente Ceneral CN-08)
FSA 25023 S	DAEWOO - DTH 14Q2FS / DVX 14F6N
@ KFT 2AA 293X	HPS 1403G / 2003G - (Vide Equivalente Aiwa - AW-03)
FSA 28014M	DAEWOO - DTH 20QTFS
MC-FBM-001	TVP5C, TVP6/B/C, TV65/AUDAX
MC-FBC-002 MF-1799	TVP7, TVP7B
MC-FBM-003 BSH12-01	TVP8, TVP12, TVP12B/VS
TAT 2104	HPS 2118, HPS 2185 FS / BLK 2105, <b>HPS 2171 (DUPLICIDADE)</b>
KFT 4AW 371Y	HPS 2912B
TAT 14101A	(Vide Equivalente SH-21)
TAT 2982A	HPS 2982 , 2991 , TVD 2911VS , TP 2958
TAT 2909 A	HPS 2909 / 2971 ( <b>DUPLICIDADE</b> )
TAT 2971A/B	TVD 2901 (DUPLICIDADE)
BSC 27-G0101	BLUE SKY - TC PL 2919 P (Vide Equivalente Ceneral CN-12)
FUH 30A005	
MC-FBM-004	
MC-FBM-018 (VM-14AF)	
BSC 29-0192F	CCE - HPS 2991FSC, HPS 2997FS
TAT 3301A	HPS - 3301
BSC 29-0157E	HPS 2985/B/C/D ; TVD2901F ; HPS 2988 (DUPLICIDADE)
CFB2-005 / 43-74-1003	TVP 105
<b>MTI LTC-042</b>	<b>HPS 2971 "CUIDADO" DUPLICIDADE LER MANUAL</b>
<b>MF-6950B</b>	
<b>BSC29-0178V</b>	<b>PROVIEW TL29N6T / TL 29NSP</b>
<b>BSC25-0274D</b>	<b>BLUE SKY/ CCE HPS1471E/F/G HPS1473D</b>
	<b>CINERAL, BAKOSONIK, CYBER VISION</b>
FO 1415 (DNF) BSC 23-6910 BSC 25-2701	CINERAL - TC-1432 / 1433 (Vide Equivalente Blue Sky - CCE-31) 14TF
@ 154-164 F	CTVG 5050 ( Vide Equivalente Panasonic - P S-11 )
@ FSV 20 B 012	( Vide Equivalente Samsung - SS-14 )
@ FSV 20 B 013 C1226214A C1226215A SN: 11226178	CINERAL - TC-2032 / 2033V (Vide Equivalente Blue Sky - CCE-26)
FSA 27018 M DCF 2077Z	1411 / 1422 / 2011 / 2022 CVT 1485
KFS 61262	CINERAL - PVM 2050 / 2051 BR, CVT 2085 (Vide Equivalente Paxan PX-08)
FCM 20A010	CINERAL - 2070
BSC 28-2101 C1226216C	CINERAL - TC-2932 / 2933 (DUPLICIDADE) / 29BD (Vide Equivalente CCE-51)

## CÓDIGO

## MODELO

**CINERAL, BAKOSONIK, CYBER VISION**

**FFA 94024L**  
**DFF 98014**  
**BSC 28-N2313R**

TS 2975  
 14" E 20" CINERAL  
 CINERAL/BLUESKY/CYBERVISION - TS2932/2933 (DUPLICIDADE)  
 TC 2933 (DUPLICIDADE)

**BSC 27-G0101F**

TC PL2919P / **PL 2910P**

**MCG-21A26**

SN: 11226230

**PWL - 15**

BSC 25-N0522

CINERAL - TS 2977  
 CYBER - VISION MDTF 2948

**BSC 28-N2328**

BLK 2932

**OV2094-1**

(08301FT----)

CINERAL - 2070 / MDTF 2948 / TC 2034 / TC 2048 CYBER  
 TCPL 2110 / TC 1470 M / TC 1433 N / TC 2023

**MCJ-29A005**

TS 2932 / TS 2933

**BSC 24-N0102C**

( OV 2094 )

CINERAL

**BSC 25-N0302**

( OV 2094 )

CINERAL

**BSC 30-N2570**

6174917003A

CINERAL

**BSC 29-0157E**

CINERAL / CYBER CB 2905

**3220004**

CINERAL VT 0950 M

**BSC28-N2313A**

**CINERAL**

**CONTINENTAL, COUGAR, EMERSON**

**101-21002-03 A**

LCE CF-0359

EMERSON

**FCK 1415 JL**

**154 - 189 H**

EMERSON - 2122 C, TECSONIC T14RWC, SEMIVOX TS 14C1R  
 3352 Z

**3214014**

GT - 9313 ( CONTINENTAL )

**3214015**

EMERSON - 1465B

**154 - 138B**

EMERSON - TC-1465

11226086

EMERSON - TC-1405A

**3.220.030**

EMERSON - TC-2066

**F 2005 CE (H)**

COUGAR - CTV 1413 / 2013

**3.220.023**

VT 2020

**GOLDSTAR**

**154 - 164 E**

FC 1445

GTV 5050, CB 14

**154 - 177 J**

CP1413, CP14 A 13, 14 A 40, 14 A 80, 14 CB 80, 14 A 82, 20 B 70,  
 20 CB 80, 20 A 82

(Vide Eq. Gradiente - GT-02/ LG-02/ Philco - PC-04/ Samsung - SS-06 )

@ **154 - 179 M**

CP 29 C 10 ( Vide Equivalente LG-03 e CCE-12 )

## CÓDIGO

## MODELO

## GOLDSTAR

**154 - 207 A****154 - 207 E****154 - 375 A**

CANGURU KP 14V30 , 20A80

(Vide equivalente Gradiente - GT-03)

( Vide Equivalente Gradiente - GT-04/ LG-04/ Samsung - SS-07 )

**154 - 375 C**

( Vide Equivalente LG-05/ Samsung - SS-08 )

**154 - 168C**

GOLDSTAR - CNT 9175

**GRADIENTE, JVC, MONITOR DE SEGURANÇA****FCV 1410 E 06**

( 571 395 001 902 )

@ **154 - 177 J**

( 571 476 001 902 )

GT 1410, GT 1411, 14 C 5170

( Vide Equivalente Telefunken - TF-01 )

GT 1420, 1422, 2020, 2022, 2025

(Vide equivalente Goldstar - GD-02 / LG-02 / Philco-PC-04 / Samsung - SS-06)

@ **154 - 207 A**

( 951 167 001 901 )

GTV142 (TV E VIDEO)

( Vide Equivalente Goldstar - GD-04 )

@ **154 - 375 A**

( Vide Equivalente Goldstar - GD-05/ LG-04/ Samsung - SS-07 )

**FCV 2010 E 02**

FCV 2011

( 571 391 001 902 )

**FCV 2010 E 09A**

230934

**CJ 27773 / 00AJ1**

CE 42205-002

G 27327-063F

**CJ 27898**

( 571 418 001 902 )

**CJ 28069****CJ 28111****CJ 28212**

( 571 448 001 902 )

**CE 41899-00A****CE 42211-00B**

CE 42031-00C

571 414 001902

**CE 42674-001J1**

( 571489001902 D )

**47105380**

BSC 26-5620

( 571 439 001 902 )

GT 1410, GT 1411, GT 2010, GT 2011, GT 2015

20 C 5170

( Vide Equivalente Telefunken - TF-02 )

( Vide Equivalente RCA-08 / Zenith -ZT-01 )

JVC - C 1485BR / C 1484

HRM 29 PS / HRM 33PS / HRM 37PS

JVC - 31BX4

AV 2196 SAH, AV-T-2172

JVC C 1486, CT 1471

HRM 290 PS / HRM 330 S / HRM 370 PS

JVC - AVB 2973 - AVB 3373

GRADIENTE - 335 COM PIP / JVC - AV 31BP4 / AV-3150

GT - 2825 / 2925

HT - M 277S / 299S / 29 Mi / 29i

JVC- AV-T2977

HRM 290 S

## CÓDIGO

## MODELO

## GRADIENTE, JVC, MONITOR DE SEGURANÇA

TCV 50 B 01

FCV 1422L01

6174V - 8004 A

6174V - 8004 D

6174V - 8005 C

( 570007001902 )

QQH 0025-001

CE 42374-00-CKJ1

6174Z - 6012 Q

CE 41735-00A

2436214 (MD14L)

JF 0501-19555

FUH 30A006

FUH 30A005

6174Z - 6512B

6174Z - 6012X

FFA 97031L

FFA 97038L

6174Z - 6051B

JF0501-19563

BSC29-0177H

JVC - 2120 (Vide Equivalente Pekonic - PX-05)

2030 / 2033 / M - 20i / 1430 / 1433 / 14 Mi

Monitor de Segurança - SM-14 / CFTVSM-20

( Vide equivalente LG-18 )

HT-M 344S

JVC - AV 35BP4U / GRADIENTE - HRM - 37PS

Monitor de Segurança - 29MI (DUPLICIDADE)

GT 29S / S-28

GT 2010

GBT-2011 / TV-2021 / TV-2020 - TV-1421

TF-2953

TV - 2925

TV - 2924

NEXT 29L / TV 2920

TV 2922 / GBT 2911 / TV 2920

TVD 2951

TF 2952

TF 2150

2960

## GRUNDING

2436912

NCO 8L

1142.5046

GT 2012 A

GI 1412 / 2012 / 2112

( TV + VIDEO ) TVR 3701 SV , TVR 3710

## KIREY, FIRST LINE

FC 1412

FC 1426

FA 2017

FA 2019

FIRST LINE ( Vide Equivalente Semivox - SS-02 )

KTV 1414 / TS 14 CIR

FIRST LINE - T 20 AW ( Vide Equivalente Semivox - SS-19 )

KTV 2020 / TS 20 CIR

## LG

154 - 103 D

154 - 103 F

@ 154 - 177 J

CP 29 C 42 / P

CP 14 B 84, CP 20 B 84, CP 20 B 85, CP 20 K 40, CP 14 A 82

(Vide equivalente Gradiente-GT-02/Goldstar-GD-02/Philco-PC-04/Samsung-SS-06)

@ 154 - 179 M

CP 29 C 84 M, CP 29 C 85 M, CP 29 C 85

(Vide equivalente CCE - 12 / Goldstar - GD - 03)

@ 154 - 375 A

(Vide equivalente Goldstar - GD-05, Gradiente - GT-04, Samsung - SS-07)

CP 20 J 20

CÓDIGO	MODELO
	<b>LG</b>
@ 154 - 375 C	( Vide equivalente Goldstar - GD-06, Samsung - SS-08 )
6174Z - 6002 C	SM - 14
6174V - 6002 G	CP 14 K 40, 14 K 42, RP 20 CB 62 (DUPLICIDADE)
<b>6174Z-8005C</b>	
6174V - 6002 J	RP 21 CA 85
6174V - 6002 U	RP 20 CC 20 , 20 CB 200
BSC26-N2121(N)	
6174V - 6003 J	CP 29 K 30
BSC28 - N2307	
6174Z - 6005 D	CN-29 Q 10P , 29 Q 12P
6174Z - 6012 D	CP 29 C 85
@ 6174Z - 6012 F	( Vide Equivalente Philco - PC-33 )
3210-94714-010	
6174Z - 6012 N	CP 25 Q 20
6174Z - 6031 A	CP 29 Q 50 , CP 29 Q 20 (DUPLICIDADE)
6174Z - 6032 A	CP 21 Q 22
6174Z - 6040 B	CP 14 J 52
@ 6174Z / V- 8004 A	CP 14 B 85, CP 20 B 15, CP 20 B 85
6174V - 8004 D	CP 20 J 52 , 20 K 40 , CP 20 J 50
6174V - 8005 C	20 K 70 , 20 B 86 , 24K70
	( Vide equivalente Gradiente - GT-17 )
6174Z - 6040 C	
6174V - 6003 M	CP 25Q22
BSC 30-N2514	
6174Z - 6051 B	29"
JW-3	
6174V - 7001 A	CP - 20B15 / 20K40 / 20B85
FSA 39012S	
6174Z - 6012 U	
4410Z - A001 G	RETRO 42" 1 ENTRADA / 1 SAÍDA (CAPACITOR)
6174V - 5003 B	29CC25, 29CC26, 29CC90
BSC 28-N2324	
6174V - 5003 G	29K30A
BSC 28-N2331	
6174Z - 6035 D	WP 3210 P , WP 32Q10P
<b>6174Z-T6035D</b>	
6174V - 6006H	CP 15Q90A, 21FB32
BSC23-N0121	RP 21FD10
6174Z - 6400B	RETROPROJETOR
6174V - 6006C	CP 21Q24A
BSC23-N0115	
6174Z - 5004A	29" CP 29Q54 (duplicidade)
6174V - 6003X	
6174V - 5003L	
BSC 28-N2334	
6174V - 5003A	RP 29FA30A
<b>BSC28- N2325</b>	
6174Z - 6004F	



CÓDIGO	MODELO
<b>6174V - 6006J</b> BSC 26-N2123	
<b>6174V - 5003R</b> BSC 25-N1537	RP 29FF80 , RP 29FA35A
<b>6174V - 6006V</b> BSC 25-N1651	RP 21FS4R-L6 <b>CP 15Q 90</b>
<b>6174V - 5013A</b> BSC 28-N2355	CP 29K35A
<b>154-238A</b>	CP 29H90P
<b>4410Z - A001P</b> Divisor 1 entrada e 3 saídas	
<b>6174V - 6017A</b> JF 0501-19975	RP 14CB25 20CD2R
<b>6174V - 6010C</b> 6174Z - 6035W	RI 34FC32P
<b>6174V - 5007B</b> 6174V - 5007A	RETRO 54NA40PA 44" <b>RP 57NP60P</b>
<b>6174V - 6010F</b> 6174Z - 6035X	RP 29FC40P
<b>6174V - 6010A</b>	RP 32FZI224
<b>6174V - 6010D</b>	<b>ATENÇÃO: LER MANUAL! RP 32FC12P</b>
<b>6174V - 6006W</b>	RP 21FE85G
<b>6174V - 5017A</b> BSC25 - N1545	29 CC 9 LR
<b>6174Z - 6005S</b>	<b>CP 29Q30B</b>
<b>6174V - 5013C</b> BSC30 - N2558	<b>RETRO RP 44NA48-P</b>
<b>BSC26 - N2137</b> EBJ 37 038602	<b>CP29FX5CL (DUPLICIDADE)</b>
<b>BSC28-3965N</b>	<b>CP29FX5CL (DUPLICIDADE)</b>
<b>154-207C</b> 154-375A	<b>CP- 20B84</b>
<b>6174V-6003T</b>	<b>CP - 29Q12P</b>
<b>BSC26-N2138</b> EBJ 37 038603	<b>29FS 4RLG</b>
<b>BSC 25-N0363</b> EBJ 34 806701	<b>21 FU 4RLG - 21 FV 1R</b>
<b>BSC 24-3368J</b> EBJ 38 957401	
<b>4410Z - A001L</b> Divisor 1 entrada e 3 saídas	
<b>mitsubishi , EVADIN, AIKO</b>	
<b>334 B 06209</b> 334 B 06208	TC 2001, 2002, 2003, 2020, 2021 , 2602
<b>334 B 07409</b>	
<b>334 B 07601</b> 840.000.141.142	VS 403R (40 Polegadas) / TC-3701
<b>334 B 08201</b> (Foco ALTO)	TC 1441, 2030, 2031, 2034, 2040, 2041 ( Foco Alto )
<b>334 P 11501</b>	TC 2602

## CÓDIGO

## MODELO

## MITSUBISHI , EVADIN, AIKO

<b>334 P 13001</b> 334 B 08202 334 P 13002 (Foco BAIXO)	TC 1441, 2030, 2031, 2034, 2040, 2041 ( Foco Baixo )
<b>NF 7404 E</b>	TC 2050, 2051, 2090, 2091, 2094
<b>334 P 18102</b> ( 2 FOCUS )	29 FS
<b>334 P 18504</b>	TC 21 FC , 2121 FC
<b>334 P 19501</b>	TC 1492 / 2034
<b>334 P 20001</b>	TC 1492, 1498
<b>334 P 20101</b>	TC 2051, 2054 , 2060
<b>334 P 21202</b> <b>334 P 21203</b>	29" TC - 2999 / TC - 2998
<b>334 P 229B1/C1</b>	TC 1499, 2097, 2098, 2099, 21 S
<b>334 P 22901</b>	TC - 2198
<b>334 P 24801</b> ( 840-000671-247 )	TC 2909 C
<b>334 P 25901</b>	TC 1409, 2009
<b>334 P 27201</b> KFT 3AA 226C	TC 2018 , 2018 PS
<b>334 P 27301</b> CT - 8932	TC 1418 , 2018 , 2118
<b>334 P 27401</b>	TC 2918 P S
<b>334 P 23101</b>	33" TC-3398 (DUPLICIDADE), TC-3498 , CS 31303
<b>KF 58383 P</b>	33" 3398 (DUPLICIDADE)
<b>334 P 265A10</b>	TC 3309
<b>334 P 272A10</b> BSC 27-0107A	
<b>BSC 27-0104B</b>	TC-2004ST / 2010 / TC - 1410
<b>JF0501-3803</b>	
<b>334 P 23105</b>	
<b>BSC 27-0167S</b> 840-00001-247	TC 2910
<b>BSC 27-0177R</b>	
<b>BSC 27-0106R</b>	
<b>6174Z-6007A</b>	TC 2018
<b>334 P 16809</b> <b>KFT 3AB-126C</b>	CS-3520

## PANASONIC

<b>OLF 04508-F</b>	TC 27G31V , 33V60, <b>29V60</b>
<b>TLF 14427 F</b>	PVM 2050 TV + VÍDEO (CANGURU)
<b>TLF 14470 F</b>	29 V 50 , 29 V 60
<b>TLF 14531 FV</b>	TC 209 S, 210 S, 210 US, 215 M, 211 N, 212,
9 pinos	TC 212 M, 213, 214 , 215 N

CÓDIGO	MODELO
	<b>PANASONIC</b>
<b>TLF 14532 F</b>	TC 141 N, 142 M, 143 M, 161 M, 162 M
<b>TLF 14533 FV 2</b> 9 pinos	TC 20 C1, TC 20 D1, TC 20 R1, TC 214 M, TC 214 MU, TC 214 S, 215 N
<b>TLF 15434 F 2</b> 9 pinos	TC 144 M, 145 M, 146 M, 163 M, 164 M, 165 M
<b>TLF 14731 F</b> 9 pinos TLF 14731F-1	TC 14R1 M, 144, 145 M, 146 M, 163, 164 M, 165 M
<b>TLF 14731 F-1A</b> 9 pinos	TC 14 C1, 14 C1U, 14 D1, 16 C1, 16 D1, 16 D1V
<b>TLF 14731 F-3A</b> 10 pinos	14 C2, 14 D2, 14R1M, TC-13C1U, TC-14D1U, TC 20CZ 1401MN / 1402 MN , TC 1433 ( Vide Equivalente Bakosonic - CN - 02 )
<b>154 - 164 F</b> KFS 60893	TC 20 A2, 20 C2, 20 D2
<b>TLF 15531 FA</b> 10 pinos	TC 29 AS2, TC 29 AV1
<b>TLF 15540 F-A</b> 10 pinos	TC 20 AS2, 20 AS4
<b>TLF 15541 F</b> 10 pinos	TC 20 BS 5, TC 20 C 4, TC 20 C 5, 20 D 4, 20 D 5
<b>TLF 15564</b> 10 pinos	PT - 51 G 40 U ; TVC 21 V 50
<b>TLF 15615 F2</b>	TC 14 C 4, TC 14 C 5
<b>TLF 15626 F</b> 10 pinos	TC 14 B 7, TC 14 C 20, TC 20 A 7 (duplicidade) , TC 20 B 7, TC 20 C 20, TC 20 C 7, TC 20 C 21 , 20 C 6
<b>TLF 15644 F1</b> TLF 15644 F	TC 20G7 14A8
<b>TLF 15646 F</b> 9 pinos	14A9 , 14A10, 14A12 (DUPLICIDADE)
<b>KFT 2AB 095F</b>	14A10
<b>KFT 2AB 281F1</b>	TC 20 A 8, 20 A 12 (TRIPLICIDADE) / TC 20A01
<b>KFT 2AB 287F1</b>	TC - 20G9 (DUPLICIDADE) , P S 20G11
<b>KFT 3AB 096F</b>	TC 20A9 , 20A10P , 20A12 (TRIPLICIDADE)
<b>KFT 3AB 119F1</b>	TC 29 A 8 , TC 29A9 (DUPLICIDADE) , 29 A 7
<b>KFT 3AB 280F1</b> KFT 3AB 281F1	TC21G11 (DUPLICIDADE), 27G23W , TC29A9 , 29G9L, 29G11, 29G12, 29A12 <b>29A10 / 29A11/ 29A12</b>
<b>KFT 4AB 055F</b>	TC 14 C 6, TC 14 C 20, TC 20 C 6, TC 14 C 7, TC 14 A 7 , 14 C 21
<b>KFT 4AB 143F</b>	TC 182 M, 205 M, 205 S
<b>TLF 4 G 503 F</b>	TC 182 N, 205 N, 206 A, 206 B, 207, 208 M, 211 M
<b>TLF 6028 F</b> 9 pinos	TC 20G9 (DUPLICIDADE)
<b>TLF 6522 FN</b> 9 pinos	14G7 / PVM 1327 / PVM 1347
<b>KFT 3AB 054F</b>	CTV31L4 / 21G7 TV+VCR DUETO , PVM 2047
<b>KFT 2AB 073F</b>	29"
<b>KFT 3AB 074F1</b>	TC 14 A 12
<b>ZTFN 05004A</b>	TC 20A12 (TRIPLICIDADE)
<b>KFT 2AA 425F</b>	TC 20A12 (TRIPLICIDADE)
<b>KFT 2AA 427F</b>	TC 14A12 (DUPLICIDADE)
<b>KFT 3AA 426F</b>	TC 20-KL03 / TC 20-KM03
<b>KFT 3AA 428F</b>	TV + VCR CTV 14L3
<b>ZTFN 32010A</b>	TC-20A7 (DUPLICIDADE)
<b>ZTFN 33005A</b>	TV + VCR PV-M2048/2058
<b>TLF 14767F</b>	TC 29KM03 , TC 29KL03
<b>KFT 3AB 080F</b>	
<b>KFT 3AB 138F</b>	
<b>KFT 4AA 448F</b>	

## CÓDIGO

## MODELO

## PANASONIC

KFT 4AX 242 F2

KFT 4AX 242 F3

ZTFN 82007 A

ZTFN 82001A

ZTFN 35011A

ZTFN 35007A

KFT 5AA 369F

KFT 5AB 106F

KFT 6AB 056F

KF 4867 C

TC 2922LB

TC 25P22LB

TC 20A04 , TC 21FJ30L

TC 29KL04 , TC 29FJ30L , TC 29KL05

33" TC 32SX31E

TC 33ZB , TC 33V8

TC 36G32

## PAXAN / PEKONIC / PRECISION / BRASSONIC

E 1051

@ DCF 1577

PAXAN - 14 AV 49 B

PRECISION - PVM 1451 BR ( Vide Equivalente CCE - 13 )

@ DCF 2077

DDF 9802A

KFS 61115

PAXAN - 20 D 49, 21 M 4 SD

PRECISION - PVM 2051BR

(Vide Equivalente CCE-28, Philco - PC - 07, Telefunken - TF - 03)

TCG 30 B 02

TCG 30 B 13

@ TCV 50 B 01

FCV 1422L01

KFS 61269

DFF 98020A

@ KFS 61262

PEKONIC - CT 1000

PEKONIC - CT 1400, 1409

(Vide Equivalente JVC - GT-16)

PRECISION

21M49

PAXAN - 21M49B

( Vide Eq. Cinerál - CN-06 )

PRECISION - PTV 2085 RNC

JF 0503

122-5020503

## PHILCO

BW 00103

( 3210-79093-00-0 )

FCM 14 B 007B

3213009

FCK 14 B 025A

PCS 2952

( Obs: EM ALGUNS CASOS SERVE P/ PCS 2700 )

PVT 1400 / 1410 / 1412 / 2014

DUETO PVT 1418

154 - 177 J

14C82RC, CPT 2030R, CPT 1430, 2030, 2040, 2130, 2040R

PAVM 2140 ( ARGENTINO )

( Vide Eq. Goldstar - GD-02/Gradiente GT-02/LG-02/Samsung SS-06 )

154 - 279 F

154 - 279 S

FCM 20 B 043

@ DCF 2077

DDF 9802A

KFS 61115

PCS 2950

PVT 2014, PTVR 2400 , 2410

C1411R,C1411T,CL1411,CL1411R,CP1411R,CP1411T,CP2011,

CP2011R,CP2011T

(Vide Equivalente CCE-28,Paxan e Precision - PX-03,Telefunken - TF-03)

CÓDIGO	MODELO
<b>OV 2094 / D1</b> 11 PINOS ( 3210-87879-01 B ) ( 3210-E2237-01-4 ) ( 3210-90815-01-7 )	PCM 1448, 1451, 1456, 2048, 2051, 2056 PCR 1447, 1449, 2047, 2049 PCS 2050, 2060 TP-1452N / 1453S / 1454 / 2053S / 2054 / TP-1452N CHASSIS CPH-061 CHASSIS CPH-06M
<b>OV 2094 / D1 - B</b> 11 PINOS <b>08292FT----</b>	
<b>OV 2094 / D1 - C</b> 11 PINOS <b>08292FT----</b>	TP-2054
<b>OV 2094 / D1 - F</b> 11 PINOS <b>08292FT----</b>	PCM 2051
<b>OV 2094 / D1 - H</b> <b>08292FT----</b>	TP-2052N
<b>OV 2094 / D1 - I</b> 11 PINOS <b>08292FT----</b>	TP-2052N
<b>OV 2094 / D1 - N</b> 11 PINOS <b>08292FT----</b>	
<b>2436772 /</b> <b>3210-61313-001</b> OV 2094 / D3	PAVM 2920 PCK 1444 HI VISION
<b>3210-61315-001</b> OV 2094 / D3	PCM 2043, PCS 2168
<b>3210-61317-00-04</b> ( CHASSIS-CPH-05 )	PCS 2700 (Em alguns casos usar BW00103)
<b>B 32 - 3409</b> B 32 - 3403	CTH - 001 (16 e 20 Polegadas) PC 1401, 1402, 1403, 1601, 1602, 1603, 2001, 2002, 2003
<b>B 32 - 3412 - 002</b> B 32-3431	PC 1405, 1406, 1416, 1421, 1425 U, 1426 U, 1427U , PAVM 2140 PC 1428 U, 1603, 1605, 1606, 1613, 1616 , PAVM 2140V/ST
<b>B 32 - 3413 - 002</b> B 3210-61297-00-3 (T2) TVC / 23	PC 2004, 2007, 2008, 2013, 2015, 2016 U, 2017 PC 2018, 2025 U, 2026, 2027 U, 2028U , 2040U PAVM 2040 (DUPLICIDADE), PAVM 2140
<b>B 32 - 3415 - 004</b> <b>B 32 - 3418</b> B 32 - 3426	PB 17 A 2, 20 A 2 (Filamento 6V) PAVM 2054 , PAVM 2040 (DUPLICIDADE), 2050, 2052
<b>B 32 - 3427</b>	PAVM 2400U , 2040 (DUPLICIDADE)
<b>B 32 - 3437 - 001</b>	PC 1435, 1436 , CHASSIS 03
<b>B 32 - 3438 - 001</b>	PC 2035, 2036, 20 R 36
<b>B 32 - 3439 - 001</b>	PC 2136, PAVM 2160

CÓDIGO	MODELO
<b>B 32 - 3448 - 003</b>	PC 1437, 1438, 1439, 1441, 1442 , CHASSIS 04
<b>B 32 - 3449 - 003</b>	PC 2037, 2038, 2039, 2041, 2042, 2138, 2142, 20 R, 20 R 37
154 - 177 W / <b>TCAM62162</b>	20R38, 20R42, PAVM 2141, 2142, 2162, 2164, 2166, CPH04, 20R48
<b>B 32 - 3452</b>	& PB 17 A 2 (Filamento 11V) (LER MANUAL)
<b>B 32 - 3453 - 001</b>	CPH05 PC 1443, 1444, PC 1445, PCM 1446
<b>B 32 - 3454 - 001</b>	CPH05 PCM 2043, 2044, 2045, 2046, 2144,2145, 2146, PCS 2168
1.35.52113-00	
<b>6174Z - 6012 F</b>	PCS 2956 P / 3320 , PCS 2958 P / 3322 / PCS 2976
FFA 97017L	( DUPLICIDADE )
3210-94714-010	( Vide equivalente LG-13 )
<b>A 6194 - 010</b>	PCS 2976, PC-A6174
JF0501 - 2156	(DUPLICIDADE)
3210-A6194-010	PCS 2956 , PCS 2979
( FFA 99057 M )	
<b>FFA 65025 L (1)</b>	
<b>OH08A4 J</b>	<b>LER MANUAL</b>
<b>4LXXXX</b>	
( 2 FOCUS )	PCS 2902, PCS 2802/56
FFA 65025 L (1)	TPF 2901 / V , TPF 2902 / V , TPF 3201 / V , TPF 3211 , 3221
0K0102 S	& TPF 3421
0K1707 S	
FFA 65025 D	
3210-A4660-01-3	
LER MANUAL (CUIDADO)	
FFA 65025 L (1)	
0H09B1 J	
0H0905J	
<b>FFA 65025L (1)</b>	<b>É DIFERENTE</b>
<b>OG36A1J</b>	
<b>OG06A1 J</b>	<b>CUIDADO!!!! NAO DISPONIVEL</b>
<b>FFA 97017 L (1)</b>	PCS 2956 N / 2902 N (DUPLICIDADE)
(DUPLICIDADE)	
<b>OA20A3J</b>	
<b>OV 2094 / D1 - L</b>	TP 2053
10 PINOS	
08273FT----	
08381FT----	
<b>FFA 97035 L</b>	TPF 2901N / 2902N (DUPLICIDADE) / 2921 / 2922
3210.A4941.01-9	PCS 2956N / 3320N / 3320V / 3322N / 3322V
3210.A4941.02-7	DVS 340DW
(DUPLICIDADE)	
<b>OV 2094 / D1 - D</b>	
11 PINOS	
<b>08292FT----</b>	

CÓDIGO	MODELO
<b>FTE - 09A008</b> 3210009	PCR 1048
<b>2437094</b> 3208.6141.2007.16.97.1	PCS 3300N , 3302N
<b>OV 2094 / D1 - A</b> 11 PINOS <b>08292FT----</b>	
<b>OV 2094 / D1 - A</b> 11 PINOS <b>08292FT----</b>	
<b>OV 2094 / D1 - G</b> 11 PINOS <b>08292FT----</b>	
<b>OV 2094 / D1 - M</b> 11 PINOS <b>08292FT----</b>	
<b>FFA 65025 L</b> 3210.97177.016	<b>LER MANUAL</b>
<b>OV 2094 / D1</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - A</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - B</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - C</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - D</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - F</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - G</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - H</b> 10 PINOS 08273FT---- 08381FT----	

CÓDIGO	MODELO
<b>OV 2094 / D1 - I</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - M</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - N</b> 10 PINOS 08273FT---- 08381FT----	
<b>OV 2094 / D1 - L</b> 11 PINOS	
<b>OV 2094 / D1 - O</b> 08272FT---- 08273FT---- 08381FT----	TP - 2051
<b>JF 0501 - 19277</b> 3210-F4118-01-09	PCS 2976 / 2976S / 2978 / 2996S / TPF 2922 / 2121
<b>2437428</b> QH 15L	
<b>JF 0501 - 19192A</b> 3210G0940018	TP 2054 / <b>TP 1454</b>
<b>B3210-61306-010</b>	PC 20R43, PAVM 2166
<b>FEA 737</b>	DSV 34" C/ PIP
<b>FSV 20B018</b>	PVT 2018, 2028
<b>JF0501 - 19321</b>	TP 1410 / <b>2130/2140</b>
<b>JF0501 - 19323</b>	TPF 2130
<b>FFA 99062M</b>	
<b>FFA 65035L</b>	<b>DVS 340 DW</b>

## PHILIPS

<b>BW 00101</b> ( 4806-140-170-42 ) ( 4822-140-10506 ) ( 4822-140-10511 )	29GX 1892 / 1895 / 1898
<b>13620004A</b> ( 4806-140-170-91 )	38" 28PW858
<b>140 - 170 - 77</b> 4806-140-170-77 ( 4936 )	29 PT 752 A
<b>OV 2076</b>	20 GL 1333
<b>OV 2076 ( 20591 )</b>	33 PT 772A
<b>OV 2076 ( 20592 )</b> ( 4806-140-170-78 )	29 PT 652 A 29 PT 662 A, 33 PT 772 A



CÓDIGO	MODELO
<b>OV 2076 ( 20593 )</b> ( 4806-140-170-85 )	29 PT 652, 654, 654A, 854, 854A 33 PT 752, 33 PT 772, 33 PT 854
<b>OV 2076 ( 20601 )</b> ( 4806-140-170-72 )	29 PT 552A / 78R
<b>OV 2076 ( 20692 )</b> ( 4806-140-10672 )	33 PT 574
<b>OV 2076 ( 20732 )</b>	
<b>OV 2076 ( 20905 )</b>	
<b>OV 2076 / - A</b> 21411FT----	29 PT 658A / 78R
<b>OV 2076 / - B</b> 21411FT----	
<b>OV 2076 / B2</b>	PT 554
<b>OV 2076 / B2-C</b> 08021FT---- ( 4806-158-870-59 )	
<b>OV 2076 / B2 - L</b>	
<b>OV 2076 / B2 - O</b>	
<b>OV 2076 / B3</b>	20 PT 656 A , 29 PT 856 A
<b>OV 2076 / B3 - B</b>	
<b>OV 2076 / B3 - D</b>	
<b>OV 2076 / B3 - H</b>	
<b>OV 2076 / B3 - I</b>	
<b>OV 2076 / B3 - M</b>	
<b>OV 2076 / B3 - N</b>	
<b>OV 2076 / B3 - O</b>	
<b>OV 2076 / - C</b> 21362FT----	
<b>OV 2076 / - D</b> 21411FT----	
<b>OV 2076 / - F</b> 21421FT----	33 PT 578
<b>OV 2076 / - G</b> 21421FT----	
<b>OV 2076 / - H</b> 21921FT----	28PW6532
<b>OV 2076 / - I</b> 21362FT----	
<b>OV 2076 / - L</b> 21411FT---- 21421FT----	
<b>OV 2076 / - M</b> 21421FT---- ( 4806-140-170-89 )	29 PT 658 , 33 PT 578

CÓDIGO	MODELO
<b>OV 2076 / - N</b> 21421FT----	
<b>OV 2076 / - O</b> 21421FT----	
<b>AT 2077/ SO / 50</b> AT 2077/ 1ª VERSÃO ( 4806-140-170-31 ) ( 4806-140-170-47 )	28 GR 7580, 28 GR 7680
AT 2077/ 2ª VERSÃO ( 3832-0 ) <b>(4806-140-170-34)</b>	28 GR 7585, 7685 V 9350-BP 21 GR 7560
<b>AT 2078 ( 21151 )</b> 4806-140-170-87	29 PT 836 , 29 PT 368 21 PT 836
<b>AT 2078 / - A</b> 21391FT---- 21401FT----	
<b>AT 2078 / - B</b> 21391FT---- 21401FT----	29PT4631 (DUPLICIDADE)
<b>AT 2078 / - B</b> 21321FT----	(DUPLICIDADE)
<b>AT 2078 / B 1</b> ( 4806-140-170-63 )	25 GX 1889, PT 230
<b>AT 2078 / B 2</b> AT 2078 ( 20311 ) ( 4806-140-170-68 ) ( 4822-140-106-37 )	21 PT 230, 21 PT 232 21 PT 1663, 21 PT 2682, 21 PT 4404, 21 PT 4424 PT 212 , PT 240
<b>AT 2078 / B4</b> ( 4806-148-870-57 )	PT 534
<b>AT 2078 / B4 - F</b> <b>AT 2078 / B4 - N</b>	
<b>AT 2078 / - D</b> 21391FT---- 21401FT----	29 PT 458 / 558 (DUPLICIDADE)
<b>AT 2078 / - F</b> 21391FT---- 21401FT----	
<b>AT 2078 / - G</b> 21391FT---- 21401FT----	
<b>AT 2078 / - I</b> 21391FT---- 21401FT----	21 PT 838A 29 PT 458 (DUPLICIDADE) , 29 PT 558 29 PT 4631 (DUPLICIDADE) , 29 PT 4831 BR

CÓDIGO	MODELO
<b>AT 2078 / - M</b>	
21391FT----	
21401FT----	
<b>AT 2078 / - N</b>	
AT 2078 / - C	29 PT 558, PT 838A , PT 848
AT 2078 / - H	
21391FT----	
21401FT----	
( 4806-140-170-88 )	
<b>AT 2078 / - O</b>	
21391FT----	
21401FT----	
<b>AT 2078 / S O</b>	14 GL 1010 , 1310 , 1410
3760 - 3	16 GL 1030 , 1330
( 4806-140-170-51 )	20 GL 1040 , 1340, 1440
( 4806-140-170-75 )	CHASSI GR1 - AL
( 4806-148-870-21 )	
<b>AT 2079 / B O</b>	14 GL 1013, 1014, 1313, 1314, 1315
( 4806-140-170-32 )	16 GL 1033, 1034
	20 GL 1314
<b>AT 2079 / B 1</b>	
3895-1	14 GL 1033 , 16 GL 1333
U 9252	20 GL 1043, 1044, 1343, 1344, 1345
UV 9239/49	
( 4806-140-170-33 )	
<b>AT 2079 / B 2</b>	17 BL 2022
( 4806-140-170-35 )	
<b>AT 2079 / B 4</b>	14 GX 1610, 1616, 1618
( 4806-140-170-38 )	
<b>AT 2079 / B 5</b>	20 GX 1650 / 56 / 58 / 60
( 4806-140-170-37 )	21 GX 1660, 1665, 1666, 1668
( 4806-140-170-83 )	
<b>AT 2079 / B 6</b>	14 GL 1015
( 4806-140-170-45 )	14 GL 1316
<b>AT 2079 / B 7</b>	& 20 GL 1045
( 4806-140-170-46 )	20 GL 1346 (LER MANUAL)
<b>AT 2079 / B 8</b>	
( 4806-140-170-55 )	
<b>AT 2079 / B 9</b>	20 GL 1048 , 21 GL 1369
( 4806-140-170-59 )	20 GL 1049
( 4806-140-170-66 )	20 GL 1349
( 4806-140-170-81 )	21 GL 1639
<b>AT 2079 / B 10</b>	14 GX 1619
( 4806-140-170-61 )	

CÓDIGO	MODELO
<b>AT 2079 / B 11</b> ( 4806-140-170-62 )	14 GX 1619 20 GX 1659 21 GX 1669
<b>AT 2079 / B 12</b> ( 4806-140-170-58 )	14 GL 1018 14 GL 1019, 1319
<b>AT 2079 / S</b> AT 2079 / SO SR-143-3 SR-149-6 SR-2044 SR-3842-4 SR-3842-3 ( 3265-1 ) ( 3842-4 ) ( 4806-140-170-29 ) ( 4806-140-170-76 )	14 GL 1011, 1012, 1031, 1032, 1311, 1312, 1411, 1420 16 GL 1031, 1032, 1331, 1332 20 GL 1041, 1042, 1341, 1342, 1441 21 GL 1451, 1452
<b>OV 2094 (20662)</b> OV 2094 (20661)	PT 316
<b>OV 2094 / 31-8</b>	
<b>OV 2094 / 41</b> ( 4806-140-170-67 ) ( 4806-140-170-73 )	14 PT 100G/78, 14 PT 110A, 14 PT 111A, 14 PT 112 A, 14 PT 113 A, 14 PT 210 A, 20 PT 120A, 20 PT 121A, 20 PT 122 A, 20 PT 123A, 20 PT 220 A / 230A
<b>OV 2094 / 42</b> ( 4806-140-170-69 ) ( 4806-140-170-74 )	14 PT 212A, 17 PT 1511/1563 , 20 PT 222A, PT 324 20 PT 2682, 21 PT 232A
<b>OV 2094 / -A</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	20 PT 228 / 78R
<b>OV 2094 / AO - A</b> <b>B-C-D-F-G-H-I-M-O-L-N</b> <b>08231FT...</b>	
<b>OV 2094 / - B</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	
<b>OV 2094 / B1</b> ( 4806-148-870-56 )	PT 314 / 414, 20 PT 326 A / 78 , 20 PT 424, 20 PT 324, 14 PT 316 , 20 PT 524
<b>OV 2094 / B1 - 1</b>	
<b>OV 2094 / B1 - 3</b>	

CÓDIGO	MODELO PHILIPS
<b>OV 2094 / B1 - F</b>	
20661FT----	
20662FT----	
<b>OV 2094 / B1 - I</b>	
20661FT----	
20662FT----	
<b>OV 2094 / - C</b>	PT 218, 20 PT 428 , 14 PT 418
10 PINOS	
08301FT----	
20662FT----	
21541FT----	
( 4806-140-170-90 )	
<b>OV 2094 / - D</b>	(DUPLICIDADE)
10 PINOS	
08301FT----	
20662FT----	
21541FT----	
<b>OV 2094 / - D</b>	(DUPLICIDADE)
11 PINOS	
08231FT----	
08292FT----	
08361FT----	
<b>OV 2094 / - F</b>	20 PT 228A (DUPLICIDADE)
10 PINOS	
08301FT----	20 PT 428A
20662FT----	
21541FT----	
<b>OV 2094 / - G</b>	20 PT 228A (DUPLICIDADE)
10 PINOS	
08301FT----	
20662FT----	
21541FT----	
<b>OV 2094 / - H</b>	14 PT 418 A / 20 PT 5290
10 PINOS	
08301FT----	
20662FT----	
21541FT----	
(4806-140-170-99)	
<b>OV 2094 / - I</b>	
10 PINOS	
08301FT----	
20662FT----	
21541FT----	

CÓDIGO	MODELO PHILIPS
<b>OV 2094 / - L</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	
<b>OV 2094 / - N</b> 10 PINOS (DUPLICIDADE) 08301FT---- 20662FT---- 21541FT----	20 PT 428 20 PT 529A / 78R
<b>OV 2094 / - N</b> 11 PINOS (DUPLICIDADE) 08231FT---- 08292FT---- 08361FT----	
<b>OV 2094 / - O</b> 10 PINOS 08301FT---- 20662FT---- 21541FT----	
<b>2437202</b> ( 4806-140-170-52)	25 GX 1888 , 29 GX 1888
<b>(4806-140-170-64)</b> 3121-218-30121 EIA 232	29 GX 1899, 1999
<b>4822-140-10609</b> ( 4822-140-10567 ) AT 2079/B13 OV 2094/50	14 PV 162, 14 PV 163, 14PV 172 PV 461 / 471 20PV471/78 CANGURU
<b>531-022-82</b> 531-022-79	29 PT 762 A
<b>CTO - L / CTO - C</b> ( 4806-140-170-22 ) ( 4806-140-170-25 ) ( 4806-140-170-56 )	& (LER MANUAL) 21 CT 7675, 21 CT 7678, 28 CT 7690, 28 CT 7692 28 CT 7693, 28 CT 7694 21 CT 7470 CHASSIS CTO - C
<b>CTO - 9 ( PINOS )</b> ( 4806-140-170-23 )	& (LER MANUAL) 14 CT 6401 , 16 CT 6010 , 20 CT 6035 CHASSIS CTO - 9
<b>NCF - 10 ( PINOS )</b> ( 4806-140-170-23 )	16 CN 4435 , 16 CN 4416 , 16 CN 4066 CHASSIS NCF - 10
<b>OV 2094 / B1 - D</b> 20661FT---- 20662FT----	20 PT 324A / 78R
<b>OV 2076 (21311)</b> 3128.138.20593 ( 2 FOCUS )	34" 34PT8419
<b>JF0501-19255</b>	14 PT 3131 , 20 PT 3331
<b>JF0501-19196</b>	PT 639 / 739 / 21PT 5431

CÓDIGO	MODELO
<b>4806-140-17028</b> 3832-2 <b>JF 0501-1215</b>	21 GR 7560
<b>OV 2094 / A1-D</b> <b>OV 2094 / B1-8</b> <b>OV 2094/-H</b> (11 PINOS) DUPLICIDADE 08231FT---- 08292FI---- 08361FT----	
<b>AT 2078 / B4-2</b> <b>OV 2094/-O</b> (11PINOS) DUPLICIDADE 08231FT---- 08292FT---- 08361FT----	
<b>1142.5020</b> 4822.140.10525	14 GX 3516 , 14 GX 8510 , 20 GX 8550
<b>OV 2094 / B1-A</b> 20661FT---- 20662FT----	
<b>OV 2094 / B1-B</b> 20661FT---- 20662FT----	20 PT 324
<b>OV 2094 / B1-C</b> 20661FT---- 20662FT---- (4806-148-870-56)	20 PT 324
<b>OV 2094 / B1-G</b> 20661FT---- 20662FT----	
<b>OV 2094 / B1-H</b> 20661FT---- 20662FT----	20 PT 424A/78
<b>OV 2094 / B1-N</b> 20661FT---- 20662FT----	
<b>OV 2094 / B1-O</b> 20661FT---- 20662FT----	
<b>OV 2076 / - C</b> 21921FT----	
<b>OV 2076 / - H</b> 21362FT----	
<b>OV 2076 / - H</b> 21411FT---- 21421FT----	

CÓDIGO	MODELO
<b>OV 2076 / - I</b>	<b>PHILIPS</b>
21921FT----	
<b>OV 2094 / - A</b>	
11 PINOS	
08231FT----	
08292FT----	
08361FT----	
<b>OV 2094 / - B</b>	
11 PINOS	
08231FT----	
08292FT----	
08361FT----	
<b>OV 2094 / - C</b>	
11 PINOS	
08231FT----	
08292FT----	
08361FT----	
<b>OV 2094 / - F</b>	
11 PINOS	
08231FT----	
08292FT----	
08361FT----	
<b>OV 2094 / - G</b>	
11 PINOS	
08231FT----	
08292FT----	
08361FT----	
<b>OV 2094 / - I</b>	
11 PINOS	
08231FT----	
08292FT----	
08361FT----	
<b>OV 2094 / - L</b>	
11 PINOS	
08231FT----	
08292FT----	
08361FT----	
<b>OV 2094 / A1 - A</b>	
<b>OV 2094 / A1 - C</b>	
<b>OV 2094 (08292)</b>	
<b>JF 0501-2135</b>	21PT5431/5432, 25 PT 5531, 29 PT 4631 (DUPLICIDADE) , 29PT 4640 , 21HT5432 , 29HT4631
<b>OV 2076 / B2-F</b>	
21411FT----	
21421FT----	



CÓDIGO	MODELO
<b>OV 2076 / B3-A</b>	<b>PHILIPS</b>
<b>OV 2076 / B3-C</b>	
<b>OV 2094 / B1-L</b>	
20661FT----	
20662FT----	
<b>OV 2094/-M</b>	
10 PINOS	
08301FT----	
20662FI----	
21541FT----	
<b>OV 2094 / - M</b>	
11 PINOS	
08231FT----	
08292FT----	
08361FT----	
OV 2094 (08301)	
<b>OV 2094 / - A</b> (10PINOS)	
OV2094-1 (08301FT)	
20662FT----	
<b>OV 2094 / A1</b>	
<b>AT 2078 / - A</b>	
21321FT----	
<b>AT 2078 / - N</b>	
AT 2078 / - C	
AT 2078 / - H	
21321FT----	
<b>AT 2078 / - D</b>	
21321FT----	
<b>AT 2078 / - F</b>	
21321FT----	
<b>AT 2078 / - G</b>	
21321FT----	
<b>AT 2078 / - I</b>	
21321FT----	
<b>AT 2078 / - M</b>	
21321FT----	
<b>AT 2078 / - O</b>	
21321FT----	
<b>OV 2094 / A1 - B</b>	
<b>OV 2094 / A1 - F</b>	
<b>OV 2094 / A1 - G</b>	
<b>OV 2094 / A1 - H</b>	
<b>OV 2094 / A1 - I</b>	

<b>CÓDIGO</b>	<b>MODELO</b>
<b>OV 2094 / A1 - L</b>	
<b>OV 2094 / A1 - M</b>	
<b>OV 2094 / A1 - N</b>	
<b>OV 2094 / A1 - O</b>	
<b>AT 2078 / B4 - D</b>	21 PT 534 / 78R
<b>AT 2078 / B4 - M</b>	
<b>AT 2078 / B4 - O</b>	
<b>3128.138.20671</b>	
<b>20671FT----</b>	
<b>AT 2078 / - H</b>	
<b>AT 2078 / - D</b>	
<b>21341FT----</b>	
<b>AT 2078 / - O</b>	
<b>21341FT----</b>	
<b>AT 2078 / - D</b>	28PW6421 / 6431
<b>AT 2078 / - A</b>	
<b>AT 2078 / - B</b>	
<b>AT 2078 / - C</b>	
<b>AT 2078 / - H</b>	
<b>AT 2078 / - M</b>	
<b>21342FT----</b>	
<b>3.128.138.213.42</b>	
<b>OV 2076 / AO</b>	
<b>JF 0501-21835</b>	34 PT 8419 / 78 (DUPLICIDADE)
<b>JF 0501-19272</b>	21PT5433 / 21 PT 5435
<b>2422.531.026.13</b>	
<b>JF 0501-21133</b>	29 PT 5642 (DUPLICIDADE) / 28 PW 6441/78
<b>JF 0501-2136</b>	29 PT 5632 , 29 PT 5642 (DUPLICIDADE)
<b>AT 2078 / - C</b>	
<b>21341FT----</b>	
<b>OV 2076 / - A</b>	
<b>21362FT----</b>	
<b>OV 2076 / - A</b>	
<b>21921FT----</b>	
<b>OV 2076 / - B</b>	
<b>21362FT----</b>	
<b>OV 2076 / - B</b>	
<b>21921FT----</b>	
<b>OV 2076 / - C</b>	
<b>21411FT----</b>	

CÓDIGO	MODELO
<b>OV 2076 / - C</b>	<b>PHILIPS</b>
21421FT----	
<b>OV 2076 / - D</b>	
21362FT----	
<b>OV 2076 / - D</b>	
21921FT----	
<b>OV 2076 / - F</b>	
21362FT----	
<b>OV 2076 / - F</b>	
21921FT----	
<b>OV 2076 / - G</b>	
21362FT----	
<b>OV 2076 / - G</b>	
21921FT----	
<b>OV 2076 / - L</b>	
21362FT----	
<b>OV 2076 / - L</b>	
21921FT----	
<b>OV 2076 / - M</b>	
21362FT----	
<b>OV 2076 / - M</b>	
21921FT----	
<b>OV 2094 / - A</b>	
08351FT----	
<b>OV 2094 / - B</b>	
08351FT----	
<b>OV 2094 / - C</b>	
08351FT----	
<b>OV 2094 / - D</b>	
08351FT----	
<b>OV 2094 / - F</b>	
08351FT----	
<b>OV 2094 / - G</b>	
08351FT----	
<b>OV 2094 / - H</b>	
08351FT----	
<b>OV 2094 / - I</b>	
08351FT----	
<b>OV 2094 / - L</b>	
08351FT----	
<b>OV 2094 / - M</b>	
08351FT----	
<b>OV 2094 / - N</b>	
08351FT----	

CÓDIGO	MODELO
<b>OV 2094 / - O</b> 08351FT----	
<b>OV 2094 / B1- J</b> 20661FT----	
20662FT----	
<b>OV 2094 / B1 - M</b> 20661FT----	
20662FT----	
<b>PWL13 - B</b> 08411FT----	20PT 3331 / 20PT 4331
<b>PWL 13 - C</b> 08412FT----	
<b>PWL 13 - D</b> 08412FT----	
<b>PWL 13 - G</b> 08411FT----	PT 3496
<b>PWL 13 - H</b> 08412FT----	
<b>PWL 13 - I</b> 08411FT----	
<b>PWL 13 - M</b> 08412FT----	
<b>PWL 13 - N</b> 08411FT----	
<b>PWL 13 - O</b> 08411FT----	
<b>OV 2076 / B2 - I</b> <b>KF 58383P</b> 4822.140.10469	29 PT 554A / 78 29 SX 8674 / 29 SX 8878/79 29 PT 758 / 78
<b>AT2078 / 21391FT</b> <b>1142.5093D</b> 2422.531.02323	29 PT 338 14 PT 519 20 PT 529
<b>JF 0501-8604</b> 2422.531.00047	29PT4635 / 29PT 4643
<b>PWL - 15</b> 34111	
<b>OV 2076 / - I</b> 21421FT----	
<b>OV 2076 / - O</b> 21921FT----	
<b>3104 308 20831</b> 13929004G	36PW8521 36PW9818
<b>8228.001.3476.1</b>	

CÓDIGO	MODELO PHILIPS
<b>OV 2076</b> 21041 21041FT----	37PT 786/78
<b>JF 0501-19865</b> 2422.531.00114	14PT3336 20PT3336
<b>OV 2076 / B2-I</b> 21411FT----	
<b>JF 0101 - 85038</b> 2422.531.00067	TELA PLANA 32PW8422
<b>JF 0101 - 85040</b> 2422.531.00069	29PT8422, 34PT8422
<b>AT 2078 / - L</b> 21321FT----	
<b>AT 2078 / - L</b> 21391FT----	
<b>OV 2076 / B3 - F</b> <b>PWL 13 - A</b> 08411FT----	
<b>13620004C</b> 2422.531.98025	28PW6521, 28PW6816 , 32PW878A , 32PW6521
<b>OV 2076 / - N</b> 21921FT----	
<b>4806.440.170.91</b> 00.368.026-0001 <b>3.121.218.301.81</b>	33PT670
<b>JF 0101 - 85021</b> <b>JF 0501 - 19973</b> 6174V - 6016B	32 PW6542 / 28 PW6542
<b>JF 0501 - 19991</b> 6174V - 6016A <b>BSC23-3369L</b> <b>6174Z-14001A</b> <b>BSC29-3807D</b>	
<b>FQH21A004</b>	
<b>JF0501-3297</b>	
<b>JF0501-91911</b>	
<b>FQH-21A002</b>	
<b>FQH29A003</b>	

## CÓDIGO

## MODELO

## R C A, GE, ROADSTAR

<b>154-387 B</b>	RBA 2020
<b>FCV 2010E10</b>	TVC - 20
<b>2 G 25026</b>	RCA - CTC 186 A, F 20637N, F 20638N, F 29632N
(316 / B1G / B2F)	GE - 25G542
<b>2 G 25028</b>	RBA 33691 , RBA 33693
( B1B )	RBA 29551
T 4401 - 1HVT	
PROSCAN	
<b>JF 0501-1901</b>	ROADSTAR - K 9780
DCF 980702-BC	
<b>PN 2G 25027</b>	RCA - RBA 29551
2G25027-A3D	
<b>JF 0208 - 0208C</b>	ROADSTAR - K-9730
@ <b>FCV 2010E09A</b>	RCA - RBA 1420
230934	

## SAMSUNG , SEMIVOX

<b>FCM 1411 L 01</b>	CB 336F
FCM 1415 AL	CN 3313 Z, 3315, 3315 Z, 3316, 3329 Z, 3352Z, 3355 Z, 3357
TLF 70018F	3361, 3552 Z, 5029 Z, CB 336F
<b>FC 1412</b>	TS - 14C1R ( Vide Equivalente First Line - KY-01 )
<b>FCK 14 A 022</b>	SEMIVOX

## SAMSUNG , SEMIVOX

<b>FCK 14 A 028</b>	SEMIVOX ( Vide Equivalente Baysonic - BY - 01 )
<b>FCK 14 A 033</b>	TV SAMSUNG CN 3338V / 3339 VB - CINERAL
@ <b>154-177 J</b>	MAT 5352 E
	(Vide Eq.Gradient - GT-02/ Goldstar - GD-02 / LG-02 / Philco-PC-04)

@ **154-375 A** ( Vide equivalente Goldstar - GD-05, Gradiente - GT-04, LG-04 )

@ **154-375C** ( Vide equivalente Goldstar - GD-06, LG-05 )

<b>FSV 20 A 001</b>	CN 331, 501, CN 3348, 5038, 5039, 5048, 5066
AA 26-30004H	
FSV 14 A 001	
<b>X FSV 20 A 001 / 27</b>	TXB 2535 / 2735
<b>FCG 2045 AL</b>	20 CB 534 V / 563Z , CN 5322
	CN 5029, 5029 V, 5029 W
<b>FCM 20 A 015</b>	CN 5062, 5062 V, 5062 W
	CN 5083, 5083 V, 5083 W
	CN 5314, 5314 V, 5314 W
<b>FCM 20 A 023</b>	CN 5055 Z / CN 5050 / CN 5052
<b>FSV 20 B 012</b>	( Vide Equivalente Cinerall - CN-03 )
<b>FCM 20 B 057</b>	SEMIVOX - TS 14C2R , TS 20C2R

CÓDIGO	MODELO
	<b>SAMSUNG , SEMIVOX</b>
<b>FCM 2014 FL</b>	CN 3329 V, 3338 V, 3362 V, 3383V , HPS 14 (CCE), CN 3355 Z
@ <b>FCM 2015 CL</b> TLF 70018A	( Vide Equivalente CCE-27)
<b>FCM 2015 ML</b> FA 2040 KFS 60769	CN 5013 Z
<b>AA26-30001C</b> <b>FA 2017</b>	TS - 20C1R ( Vide Equivalente First Line - KY-03 )
<b>FTH 29 A 001</b>	CN 7202 WB, CN 7207, CN 723
<b>FTR 29 A 003</b> AA26-30002B	CN 7266
<b>FCZ 29 A 006 A</b>	29" CN 721
o <b>FTH 29 A 013 S / P</b> X FTK 14 R 005 C	SAMSUNG - 14" e 20"
oo <b>FTH 29 A 013 S / G</b> X	29 CN 765
<b>FCR 29 A 014 R</b>	CN 7226 W, CN 7230
<b>FTK 20A007P</b>	TV + VCR CANGURU MVR-4190M
<b>FCR 25A006R</b>	SAMSUNG - TXB 2525 / TXC 2516 / CN 2516
<b>FD 2139</b>	SEMIVOX - (JKR) TS-25C15
<b>FUH 29M002</b>	SAMSUNG - CL34V6PQ , CN34V6PQ , CL34Z6PQ
<b>FFA 61012K</b> FFA 61012L	SAMSUNG CL 29MZIMQ
<b>FUH 29A001F</b>	SAMSUNG CL 29M21
<b>FSV 20B001</b>	SAMSUNG
<b>FUH 29A001G</b>	SAMSUNG
<b>FOK 14B001</b>	SAMSUNG - CL21M21
<b>FUH 29V003</b>	SAMSUNG
<b>FCA 173 / AA26-00201A</b>	SAMSUNG - CL21M6MQ
<b>FQH 21A001</b>	SAMSUNG
<b>FUH 29A001V</b>	SAMSUNG
<b>FCK 1415EL</b>	SAMSUNG - DX 1332
<b>FSV 20B018</b> 3220045	SAMSUNG
<b>FUH 29V006</b>	SAMSUNG
<b>FUH 29V001</b>	SAMSUNG CL 32Z30DS
<b>FUH 29V007B</b>	SAMSUNG - RETRO
<b>FCK 1415AL</b>	SAMSUNG - M3105
<b>FCM 20A025</b>	SAMSUNG - CXB 1922
<b>FCR 25A001</b>	SAMSUNG - 25 CN 6229W
<b>FOK 14A001</b> AA26-00231A	SAMSUNG
<b>FSV - 14A004 H(S)</b>	SAMSUNG
<b>JF0501-91910A/B</b>	<b>CL 21Z43MQ</b>
<b>FUH 32V001B</b>	<b>SAMSUNG</b>

CÓDIGO

MODELO

SANYO

<b>FDA 006 N</b>	CTP 3765, 3766
<b>FDA 007 N</b>	CTP 6765 V, 6766 V
<b>FD 0059</b> AC 30050	CTP 3750, 3751, 3752, 3755, 4751
<b>FD 0060</b> AC 30051	CTP 6750, 6751, 6752, 6753, 6755, 6755V-D4KM
<b>FD 0108</b> AC 30052	CTP 3756-V-00
<b>FD 0109</b> AC 30053	CTP 6756-V-01
<b>FD 0181</b>	CLP 2128, CLP 2127
<b>F 1175 - 76</b>	CTP 3720, 3721, 3722, 6720, 6721, 6722
<b>FD 125</b>	CTP 3770, 3771, 3780, 3781 CLP 1451
<b>FD 187</b> L 40 B 03900	CTP 6050, 6051, 6770, 6771, 6780, 6781 CLP 2151
<b>L 40 A 00100</b>	CTP 3790, 3791, 3792
<b>L 40 A 00700</b> L 40 A 00710 L 40 A 00711	C 29 LH 43 B, 2997 C 33 LJ 43 B 00 C 3396
<b>L 40 B 00300</b>	
<b>L 40 B 02510</b>	
<b>L 40 B 05500</b>	CTP 6790, 6791, 6792 (20polegadas), 6796
<b>L 40 B 05700</b>	C 2796, 2996, C 29F5 AD
<b>L 40 B 00400</b> 1LBL40B00400	

SEMP (VIDE TOSHIBA)

SHARP

<b>F 005ME</b>	29" C 2999
<b>F 0017</b> F0017 MESA / MQBD	C 29 ST 54 ( COM BOBINA NO FERRITE ) FRST LINE 29FL10
<b>F 1232</b> ( Z 4034 ) 14 "	C 1402, 1404, 1417 A, 1425, 1460, 1480, 1484
<b>F 1250</b> ( Z 4035 ) 16 "	C 1604, 1615, 1616, 1625, 1660, 1665, 1686, 1690
<b>F 1251</b> ( Z 4036 ) 21 "	C 2011, 2015, 2016, 2018, 2025, 2028, 2029, 2060 C 2086, 2090, 2181, 2186
<b>F 1562</b> ( Z 4086 )	C 1425 B, 1426 B, 1430 A, 1465 B, 1487 B, 1490 A C 1425 A
<b>F 1563</b> ( Z 4085 )	TVC 1625, 1626, 1630 A, 1665, 1687, 1690
<b>F 1564</b>	C 2025, 2026, 2030, 2090 "A", 2030 A, 2065
<b>F 1693 (Z 4183)</b>	C 1492 H, 1626, 1630, 1631, 1665, 1690, 1694
<b>F 1694</b>	C 1426, 1427, 1430, 1431, 1491 B, 1410, 1410 B, 1450 B
<b>F 1802</b>	C 2877 B, 2899 A
<b>F 1833</b> ( CE- 00066 )	C 3399



CÓDIGO	MODELO
<b>SEMP (VIDE TOSHIBA)</b>	
<b>SHARP</b>	
<b>F 1881</b>	C 1413, 1453, 2013, 2017, 2018H, 2053, C 21ST54
F 1890	
F 1952	
<b>F 1894</b>	C 1482, C 1485, 1482 B, 1485 B
<b>F 1901 ( C )</b>	C 2040, 2041, 2082, 2188, 20 R 11, 20 R 12, 20 S 01
FOCO Z 4175	C 20 S 02, 20 T 51, 2052, 2053, 2092 B
154-207R / S	
<b>F 1923</b>	C 1413, 1440, 1440B, 1452B, 1453, 1467B, 1482B, 1485B, C 14R12, 14RS02, 14RS03, 14T51, 14S02
<b>F 1998 CE ( G )</b>	C 1453 / 1457 / 14 ST 57 / 1417 DUPLICIDADE
<b>F 2005 CE ( H )</b>	C 1438, 2038, 2057, 20 ST 57, 20 ST 58
<b>F 2023 ( E )</b>	C 29 ST 58 / 29 ST 98
6174Z-6279X	
<b>F 2092</b>	C 1470 B, 1626, 1630 H, 2010, 2027, 2030 H, 2035, C 2095 C 2050, 2070, 2090, 2092, 2092 H, 2097, 2199, 1412B (Vide Equivalente CCE - 60)
<b>TAT 14101A</b>	
TAT 14101A	
<b>SONY</b>	
<b>1-439-311-32</b>	KV 1449 AV
<b>1-439-416-21</b>	KV 29 XTR 300 / TR 3
<b>1-439-416-41</b>	KV 29 XTR 20 / 30, KV 2553 BM / MT
<b>1-439-416-61</b>	KV 2114 S, KV 2127 R, KV 2137 RS, KV 2161 S, KV 2110 GM
<b>1-439-418-31</b>	KV 2940 BM
1-439-429-11	KV 2945
<b>1-439-421-11</b>	KV 1483
<b>1-439-421-41</b>	KV 1440 B, KV 1441 B, KV 2163S
<b>1-439-421-51</b>	16" e 20" KV 2160 B
<b>1-439-423-11</b>	KV 2102, KV 2500, 2114, 2123, 2133, 2134, 2153
<b>1-439-423-21</b>	KV 20EX10, KV 29TR20, KV 2553BM
<b>1-439-423-31</b>	KV 29*TR30
<b>1-439-423-32</b>	KV 27 EXR 20, KV 29XTR30
<b>1-439-423-41</b>	KV 20TS27 / KV 29XTR30
<b>1-439-423-51</b>	KV 2161 / KV 2160
<b>1-439-454-11</b>	KV 27ASR10 / iS
<b>1-439-455-11</b>	KV 27XBR15 / BR65
<b>1-439-498-71</b>	KV 2955, KV 2959, KV 3459, KV 27V15, 29 V 15 STR, KV 29 V 55, KV 32 TS 35, 32XBR45, 32S10, 34 V 55
1-439-498-12	
1-439-498-21	Modelos importados até o ano de 1994 c/ potenciômetro de
1-439-498-51	foco, "32" 32V15
<b>1-439-520-11</b>	KV 32 XBR96S, KV 32 S 26, KV 35 V 35, KV 35 V 36 KV 32S36 / KV 32XBR9 / KV 32XBR96
1-453-126-11	
<b>1-453-141-21</b>	

CÓDIGO	MODELO SONY
1-453-142-11	KV 2163S
1-453-142-21	KV 2160 , KY 14MTR1
1-453-146-11	KV 27 S 10, 27 S 15, 2959T, 29 RS 10, 2970, 32S16, 32 TS 36
1-453-146-21	
1-453-207-11	& KV 2970 T, KV 32S22 , 3470, KV 3470 T, KV 32S45
1-453-238-31	NX 2609 (LER MANUAL)
154 - A 51 J	KV 2DVM - 3P ( TV + VCR ) / KV 20VM20 , KV 20VM30
AT 2078 / UO - 1	KV 1450 B ( Cinesc. Samsung ), KV 2158, 2172 S
AT 2078 / UO - 2	KV 2170 B, KV 2173 S, KV 21 B 80 , KV 21 VH5BR
( 1-453-208-11 )	KV 2159 , KV 21S85, KV 21VM5BR , KV 21VH5BR
AT 2079 / UO	& KV 1450 (Obs: Sem potenciômetro de Focus Screen)(LER MANUAL)
AT 2079 / U1	KV 1450 B (SOMENTE P/ CINESCÓPIO SONY)
( 1-453-209-11 )	KV 14B80 / KV 14VM5BR
	OBS: CASO SEJA CINESCÓPIO SAMSUNG NÃO SERVE
AT 2079 / U2	KV 140 MG
( 1-453-216-11 )	KV 200 MG
( 1-453-217-11 )	KV 205 MP
8-598-834-20	KV 29FS12, KV29FV15B, KV29V15, KV29V15B, KV29FV16B, KV 29V16B,
8-598-834-10	KV29FV100, KV29FS100, KV29FA21, KV29FS12B (DUPLICIDADE)
	KV 29FVS1 / KV 28FS15 / KV 29FS105
8-598-838-40	KV 21 FE 12 B
1.453.316.11	KV 21 FS 105
8.598.838.41	
8-598-850-00	KV 25 FV 10 B / KV 25 FV 12 B
8-598-922-00	KV 21 XTRI, KV 2152, KV 2158, KV 2159, KV 2162 ,
( 1-453-188-11 )	KV 2163 , KV 21 X TR II
( 8-598-938-00 )	
8-598-928-01	KP 41 PT 15 B ( TELÃO ), KP 53XBR45 , KV 61 V 15
8-598-939-00	
8-598-969-00	NX 2609, KV 2970 T, KV 3470, KV 3470 T, HV 2090 T
8-598-976-00	KV 29 VX 2, KTV - 33T80, KV 34T80
8-598-998-00	KV 29 T 75, KV 29 T 76 , 29T80 (NX 4005)
8-598-998-03	KV 27V66 (IMPORT.) / 29 AL 40 A
1-453-268-11	
8-598-828-00 / 20	KP53XBR200/BR300 / KP57XBR600 / KP57WV600 / KP61XBR200/ KP65XBR7
1-453-310-11	KV 29FV16B / KV 29FV30 / KV32FV30 (DUPLICIDADE) / KV 29 FA 210
	KV 29FS100 / KV 29FA21 / KV 29FS105 / KV 29FS110
1-453-338-31	KV 29FS100 / KV 32FV30 (DUPLICIDADE)
1-453-338-11	
1-453-338-21	
1-439-452-11	
1-439-533-11	
AT 2078 / UO - 4	
08111FT----	
AT 2078 / U-6	
08111FT----	
8-598-824-10	KV 34 FV 15 B / KV 38 FV 15 B / KV 34 FS 13 B / 32 FS 12 B

## CÓDIGO

## MODELO

## SONY

<b>8-598-994-00</b>	TELÃO - KP 61V85 / KP53SV75B / KP61SV85T / KP43T85 / KP53SV65B
<b>1.439.502-11</b>	KV 27TS27
1.439.498-31	KV 32TS53
1.439.502-31	
<b>1.453.524-11</b>	KV 32FV30, KV 32XBR95
<b>1.453.147-21</b>	
1.453.149-21	
<b>1.453.336-11</b>	
<b>1.453.189-11</b>	KP 61XBR48 / KP 53XBR45
<b>8.598.939-00</b>	KP 53S15
<b>1.453.267-11</b>	
<b>1.439.456-11</b>	KV 32XBR15 / KV 32XBR55 / KV 32XBR65
<b>8.597.041-10</b>	<b>KV21XTRL</b>
<b>8.597.043-10</b>	<b>KV29FS140</b>

## TALENT

**154-279C / JF0101** 29" TVP 9229

## TELEFUNKEN

<b>@ FCV 1410 E 06</b> ( 571 395 001 902 ) FCV 1411	14 C 5170 ( Vide equivalente Gradiente - GT-01 )
<b>@ FCV 2010 E 02</b> ( 571 391 001 902 ) FCV 2011	20 C 5170 ( Vide equivalente Gradiente - GT-05 )
<b>@ DCF 2077</b> DDF 9802A KFS 61115	AV 135 (Vide Equivalente CCE-28, Paxan e Precision - PX - 03, Philco - PC - 07 )
<b>AT 90 / 7 pinos</b>	Chassi: CH 801, 802, 802A
<b>AT 90 / 11 pinos</b>	Chassi: CH 841

## TOSHIBA

<b>AT 2079 / AO</b>	TV 147, 204, 207, 209, 14 A 76 MU, 14 A 82 EAV, 147 CR
AT 2079 / A2	TV 20 A 76 UM, 20 A 77SU, 20 A 82, 1022 EAV, 1455, 1458 S
AT 2079 / A3	TV 1474 AMU, 1483 AAV, 2055, 2058 S, 2066 SU, 2078 AMU
(TFB 4067)	TV 2079 ASU, 2083 AAV, 2175 CSU, 2987 CSU, 2998CSU, 1480E
(TFB 4125 DD)	TVM 1466 MU, 1467 SU, 2066 U, 2067 MU, 2067 SU, 2082 BAU
(TFB 4125 DS)	TVS 1456 M, 1457 M, 1457 S, 1458 S, 1459 ST, 1466 MU
	TVS 1466 SAP, 1468 U, 1482 EAV, 2056 M, 2057 M, 1480/1484GAV
	TVS 2057 S, 2058 S, 2066 MU, 2068 U, 2082 M, 2083 BAW / 2084
	TVS 2175 SU, 2175U. TS 149CR, 209CR, 2070, 2070E, 2080M
<b>AT 2079 / A1</b>	<b>&amp;</b> TVC 102 (Modelo novo, não é compatível c/102 TR (antigo)/ 1021 / 1022 ( Vide NF 7305 ) (LER MANUAL) / TV 7022K
<b>OV 2094 / AO</b>	TV 1484, 1491, 2084HAV
OV 2094 / AO 08231 FT ----	
<b>B 32 - 3416</b>	TVC 10 ILX (DUPLICIDADE)

CÓDIGO	MODELO
<b>B 32 - 3423</b>	TVC 100
<b>TFB 4029 AD</b>	CF 2051 A
<b>TFB 4030 AD</b>	3466 P / 3486 P
<b>TFB 4034</b>	TS 140, 141, 142, 161, 201, 202, 204, 207VS CR / TVC 165 TVC 145 - CR / TVC 160 / TVC 164 / TVC-208VS / 200A / TVC 140
<b>TFB 4048 BD</b>	TS 147, 147VS-CR, 167, 167 CSCR, 207, VS / 2, TS 168 , TS 152 , TS 208
TFB 4065	VC-145VS-A , TVC 205 , 206 VS , TVC 200
<b>TFB 4059 AD</b>	TVC 206 VS - SÉRIE F , TVC 3064 / 3485P
<b>TFB 4062</b>	TS 287
<b>TFB 4069 AD</b>	210R6B, 215R8F, 259D9B
<b>TFB 4086</b>	TS 2889F, TS 285 ST / PIP
TFB 4087	TS 289 ST
<b>TFB 4100 AD</b>	2985 S / 2996-S (DUPLICIDADE) / CN 27D48 (DUETO)
<b>TFB 4121 BD</b>	TV 2986 S , 2996 S (DUPLICIDADE)
<b>TFB 4126 BR</b>	TV 1484 , 2078 FM , 2079 FMS, TV 2083 FAV E 14", 2084HAV
TFB 4126 AE	TV 2089H / 2090 i , 2090, 2082 , 2084
TFB 4126 CS	TV 2096ST / GMS / HMS / TV 2088 I / LUMINA NOVA
TFB 4203 AJ	TV 2084 , 2085 , 2086 , 2087 , 2090
FUY 202011	
JF 0501-2417	
<b>TFB 4127 RE</b>	TV 10R22EA, 1022BAV, U8, U9
<b>TFB 4129 AD</b>	2966 S
<b>TFB 4130 AD</b>	3466P, 3486P , CE 36G18 , CN 32G90
<b>TFB 4131 DD</b>	2987 SU, 2997 SU, 2997 P
<b>TFB 4132 DH</b>	TV 2987SU, 2997P, 2997SU , 2998ASU
TFB 4132 CD	29A87, 29A97SU, 34A88P, 34A88SU
TFB 4132 DD	TV 3488P, 3888P
TFB 4132 ED	
BW 00622	
<b>TFB 4134 AE</b>	TV 1478 FM, 1483 FAV , TV 2080 E, 1488 FMU11 / TV 1484 / 1484-G
TFB 4134 AB	TV 1485 / TV - 1490 / 1482
<b>TFB 4151 AD</b>	2987 CS, 2987 CSU, 2987 DS, 2998 CS, 2998 CSU / 2987EMS
TFB 4151 BE	
TFB 4151 BH	
<b>NF 7304 ST</b>	& TVC 100 (DUPLICIDADE) (LER MANUAL)
<b>NF 7305</b>	TVC 10, TVC 100CR , 102 TR (Modelo Antigo)
<b>KF 7414</b>	& TVC 10 i L (LER MANUAL)
<b>TFB 4118 ZD</b>	29 BC 55 , 29 S 55 ST , CN 35 D 90
<b>TFB 4099 AD</b>	TVC 3064 , TVC 3485 , TVC 3485P
<b>TFB 3058B</b>	6"
<b>TFB 4156AD</b>	2955 DFP / 2956 DFP / 3455 DFP
<b>TFB 4210AH</b>	TV 2987 IMS / 2981 JAVS CHASSIS 5 e 6
BW 03041	TV 2999 / 2987 JMS
	CHASSIS LEN4-LEN5
<b>TFB 4182 AH</b>	TV 2957 / TV 2956DFP
BW02702	FOCO DUPLO

## CÓDIGO

## MODELO

**TFB 4192 AS/ AF**

FMX 32A001

**TFB 4167 BH**

BW 02003

**JF0501-21139**

TFB 4210 AJ

**TFB4198BE/AH****13320025D**

TV 2958 / TV 3489

TV 2157 BFS

**TV 2999**

## TOSHIBA

## ZENITH / GE

**@ FCV 2010 E 09A**  
230934RDA 1420 ( Vide Equivalente Gradiente - GT-06 )  
14 GE 00**9504372**CHASSIS: SAR, SAY e SAM - 2053 C222BT - 20 Polegadas,  
SAM 21494 , 2153 BT - 21 Polegadas / 2953 BT - 29 Polegadas/  
3453 BT - 34 Polegadas**95-4134-15**

PUY 5263DT , PVR 5263 - 4660 , PVR 6069 , PVY 6069

**95-4134-01**FR 3547DT / SY 3581DT /  
(FR-3587BT : NÃO É UTILIZADO FOCUS SCREEN)**95-4134-07**

38"

**95-4134-11**

EIA 343

**& SR-3547 DT (LER MANUAL) PZR 5263DT****95.4438**

FEC 22

**A 17196 - 12**

DIVISOR DE FOCUS

RETROPROJETOR 60" (LER MANUAL)  
(COLOCAR VENTUINHA)

## FLIPERAMA / ESPECIAIS

**154 - 168 G**

FLIPERAMA / VIDEO GAME / VIDEO BINGO

**KFS 60291**

FLIPERAMA / MÁQUINA FOTOGRÁFICA NEOPRINT

**3121.218.30121**

FLIPERAMA / VIDEO GAME / VIDEO BINGO

## DIVERSOS

**43-73-1001B****FCK 14 A 032****MSU1FVG213****154-279R****CF-33661**

CCE

CCE

## FOCUS SCREEN

## MAGNETRON

**2M319K / WBL13H**MAGNETRON PARA MICROONDAS - SAMSUNG  
2M219K / 2M319K / 2M210-M1 / OM75P(31) / OM75S(31)**2M219H / WBL13E**MAGNETRON PARA MICROONDAS  
2M167B M-16 / 2M167B M-147 / 2M240H / 2M210 M-62**2M219J**

MAGNETRON PARA MICROONDAS 2M2169J

**2M319J / (2M213)**MAGNETRON PARA MICROONDAS  
OM75D(10) / 2M172A / 2M213 / 2M214 / 2M218J / 2M246 / 2M319J

## CÓDIGO

## MODELO

**6174V - 8004 A****6174V - 8004 D**

6174V - 8005 C

570007001908

**BSH-7****BSH-12N05D****BSH-13****BSH-14N304L****6174Z-6012Q****TV / MONITOR DE SEGURANÇA PEQUENO**

GRADIENTE - MONITOR DE SEGURANÇA

SM-14 / CFTV / CFTV SM-20

GRADIENTE 29" MI